

MOL Report to PLMHSC – Construction Sector – November 2016 Meeting**Section 1****Reporting Month Statistics – Quick Overview**

<b>Reporting Month</b>	<b>Month Fatalities</b>	<b>Month Critical Injuries</b>	<b>Month Total</b>
<b>October 2016</b>	2	15	17

**Provincial Coordinators Comment: November 2016**

**Section 2****MOL Current Events**

- **Ontario Increases Minimum Wage**  
<https://www.labour.gov.on.ca/english/es/pubs/guide/minwage.php>
- **Workplace Violence and Harassment – Code of Practice (effective Sept 8, 2016)**  
<https://www.labour.gov.on.ca/english/hs/pubs/harassment/index.php>
- **2016-2017 Inspection Blitzes and Initiatives**  
<http://www.labour.gov.on.ca/english/resources/blitzschedule.php>
- **Safe At Work Ontario Annual Report - Results for April 2014 - March 2015 (20 April 2016)**  
<http://www.labour.gov.on.ca/english/hs/sawo/report/index.php>
- **Small Business Health and Safety Checklist**  
<http://www.forms.ssb.gov.on.ca/mbs/ssb/forms/ssbforms.nsf/FormDetail?OpenForm&ACT=RDR&TAB=PROFILE&SRCH=1&ENV=WWE&TIT=1960&NO=1960E>
- **Working at Heights Training (content reviewed March 2016)**  
[http://www.labour.gov.on.ca/english/hs/topics/heights.php?utm\\_source=molwebsite&utm\\_medium=banner&utm\\_content=spotlights\\_EN&utm\\_campaign=WorkingAtHeights](http://www.labour.gov.on.ca/english/hs/topics/heights.php?utm_source=molwebsite&utm_medium=banner&utm_content=spotlights_EN&utm_campaign=WorkingAtHeights)
- **Occupational Exposure Limits**  
<http://www.labour.gov.on.ca/english/about/consultations/oels/index.php>
- **Replacing Your Roof (content reviewed March 2016)**  
[http://www.labour.gov.on.ca/english/resources/roofing.php?utm\\_source=molwebsite&utm\\_medium=banner&utm\\_content=spotlights\\_EN&utm\\_campaign=RoofingPilot](http://www.labour.gov.on.ca/english/resources/roofing.php?utm_source=molwebsite&utm_medium=banner&utm_content=spotlights_EN&utm_campaign=RoofingPilot)
- **Alert: Elevating Work Platform Crushing Hazard (April 2016)**  
<http://www.labour.gov.on.ca/english/hs/pubs/alerts/a36.php>
- **Alert: Tire Explosion – Pyrolysis (March 2016)**  
<https://www.labour.gov.on.ca/english/hs/pubs/alerts/a34.php>

**Section 3**

**Case 1**

Def #1: Prime Seal Roofing Systems Ltd.

Def #2: Michael Salas

Def #1: Prime Seal Roofing Systems Ltd.

**PRIME SEAL ROOFING SYSTEMS LTD., 1019 Dupont Street, Toronto, Ontario, M6H 1Z7, on or about the 9<sup>th</sup> day of July, 2009, in the City of Toronto Region, in the Province of Ontario, did commit the offence of failing to comply with an order of an Inspector issued at a project located at 27 Ryerson Avenue, Toronto, Ontario, contrary to section 66(1) (b) of the Occupational Health and Safety Act, R.S.O. 1990 c.O.1, as amended.**

**Particulars: Prime Seal Roofing Systems Ltd. failed to comply with Order #5 of Premise/Project Form F.V. No. 56355418 dated July 9, 2009, issued by Inspector Drew Robertson.**

Def #2: Michael Salas

**Michael Salas, 22 Sharon Court, Brampton, Ontario, L6W 3B7, on or about the 10<sup>th</sup> day of July, 2009, in the City of Toronto, in the Toronto Region, in the Province of Ontario, did commit the offence of failing, as a supervisor, to ensure that a worker works in a manner and with the protective devices, measures and procedures required by section 26.1(2) of Ontario Regulation 213/91, R.S.O. 1990, as amended, at a project located at 27 Ryerson Avenue, Toronto, Ontario, contrary to section 27(1)(a) of the Occupational**

**Health and Safety Act, R.S.O. 1990, c.O.1., as amended.**

**Conviction Information: Prime Seal Roofing Systems Ltd.**

Date of Disposition: February 17, 2011

**Facts in Support of Guilty Plea:**

Prime Seal Roofing System Ltd. (“Prime Seal”) is a validly subsisting corporation incorporated under the laws of Ontario.

Prime Seal was at all material times, an employer, as defined by the *Occupational Health and Safety Act*. Prime Seal carries on business as a roofing contractor.

On July 9, 2009, a Ministry of Labour Inspector attended a project located at 27 Ryerson Avenue, Toronto, Ontario, for a routine inspection. This location, at 27 Ryerson Avenue, Toronto, Ontario, was at all material times a project as defined by the *Occupational Health and Safety Act*. The project consisted of the re-roofing of a residential home. While at the project, the Inspector observed four individuals on the upper roof level. The Inspector observed the guardrails were not in place and that the workers were not wearing/using a method of fall protection attached to an adequate anchor point. The upper roof level was at a height of more than three meters from the ground level. The Inspector issued, to Prime Seal Roofing Systems Ltd., Order #5 of Premise/Project Form F.V. No. 5355418 directing Prime Seal to cease all work on the project until the order to stop work is withdrawn or cancelled by an Inspector after the inspection.

On July 10, 2009, the Ministry of Labour Inspector attended the project and observed three individuals on the roof level of the same residential home. There was still a construction project at this location. The constructor was still Prime Seal Roofing Systems Ltd.. The Inspector observed that guardrails were not in place and that the workers were not wearing/using a method of fall protection attached to an adequate anchor point. The upper roof level was at a height of 14 feet above the ground level. The lower roof level was measured by the Ministry of Labour Inspector and determined to be 11 feet above the ground level. Order #5 of Premise/Project Form F.V. No. 5355418 had not been lifted and was still in effect.

Prime Seal committed the offence of failing to comply with Order #5 of Premise/Project Form F.V. No. 5355418 dated July 9, 2009, contrary to section 66(1)(b) of the *Occupational Health and Safety Act*. To wit: failing to ensure that work stopped on the project until the shop work order was lifted.

Sentencing Information:

Date of Sentence:	February 17, 2011
Sentence (per count):	\$10,000 + 25% VFS

Conviction Information: Michael Salas:

Date of Disposition:	December 12, 2011
----------------------	-------------------

Facts in Support of Conviction:

Michael Salas committed the offence of failing, as a supervisor, to ensure that a worker works in a manner and with the protective devices, measures and procedures required by section 26.1(2) of Ontario Regulation 213/91, contrary to section 27(1)(a) of the *Occupational Health and Safety Act*. To wit: failing to ensure that the workers used fall protection.

Sentencing Information:

Date of Sentence: December 12, 2011

Sentence (per count): \$2,500 + 25% VFS

## **Case 2**

Def #1: Jeffery James Newham o/a Jeff's Roofing Renovations

**Jeffery James Newham o/a Jeff's Roofing & Renovations, 1259 Elsmere Avenue, Windsor, ON N8X 4G6, on or about June 3, 2016, in the Town of Tilbury, in the Southwest Region, in the Province of Ontario, did commit the offence of failing as a constructor to ensure that the measures and procedures prescribed by section 26.1(2) of Ontario Regulation 213/91, R.R.O. 1990, as amended, were carried out at the workplace located at 17 Canal Street East, Tilbury, ON, N0P 2L0, contrary to section 23(1)(a) of the *Occupational Health & Safety Act*, R.S.O. 1990, c.O.1, as amended.**

### Conviction Information

Date of Disposition:    October 5, 2016

### **Facts in Support of Guilty Plea:**

1. Jeffery J. Newham (The "Defendant") owns and operates a sole proprietorship known as Jeff's Roofing & Renovations. The defendant's main business address is located at 111 Riverside Drive East, Windsor, Ontario
2. On June 3, 2016, Ministry of Labour Inspector Todd Mayhead was notified of a complaint at a re-roofing project located at 17 Canal Street East in Tilbury, Ontario. The defendant was the constructor of this roofing project and is a "constructor" as defined by the *Occupational Health and Safety Act*.

3. The inspector Todd Mayhead and inspector Mike Morin attended the project and observed two workers performing work on a roof of a 1.5 storey single family dwelling approximately 12 feet from the ground. The workers were observed with harnesses on, however, were not attached to any ropes or anchors. Therefore, a necessary component of a fall protection method (fixed anchors) was not installed.
4. Section 26.1(2) of Ontario Regulation 213/91, the Construction Regulation, requires that a worker exposed to the hazard of falling 3 metres or more shall be adequately protected by at least one of the listed methods of fall protection, including a travel restraint system, a fall restricting system, a fall arrest system, or a safety net.
5. Section 23(1)(a) of the *Occupational Health and Safety Act* requires a constructor to ensure that the measures and procedures required by the Act and the regulations are carried out.
6. As such, on June 3, 2016, Jeffery J. Newham o/a Jeff's Roofing and Renovations failed, as a constructor, to ensure that workers exposed to the hazard of falling 3 metres or more were adequately protected by at least one of the listed methods of fall protection.

Sentencing Information:

Date of Sentence:        October 5, 2016

Sentence (per count):    \$3,000 + 25% VFS



### Case 3

Def #1: Creditview Roofing Inc.

Creditview Roofing Inc., 53 Saint Damian Avenue, Woodbridge, ON L4H 2L5, on or about November 1, 2014, at the City of Toronto, in the Toronto Region, in the Province of Ontario did commit the offence of failing, as an employer, to ensure that the measures and procedures prescribed by section 26.1(2) of Ontario Regulation 213/91, as amended, were carried out on a project located at 928 Royal York Road, Toronto, Ontario, contrary to section 25(1)(c) of the Occupational Health and Safety Act, R.S.O. 1990, c. O.1, as amended.

#### Conviction Information

Date of Disposition: September 16, 2016

#### Facts in Support of Guilty Plea

1. On November 1, 2014, Ministry of Labour Construction Health and Safety Inspectors Christian Bell and Matthew Neundorf observed 2 workers on the roof of 928 Royal York Road in the City of Toronto in the Province of Ontario.
2. The construction project appeared to be a single family home. At all material times, the premise was a “workplace” under the *Occupational Health and Safety Act*.
3. Inspector Bell observed the height of the roof as over 3 metres, and observed the 2 workers on the roof were not protected by fall protection while exposed to a hazard.

4. The workers observed on the roof were employed by Creditview Roofing Inc.
5. The defendant Creditview Roofing Inc. (“Creditview”) was at all material times, and continues to be, a validly subsisting corporation incorporated under the laws of the Province of Ontario, with a head office located at 53 Saint Damian Avenue, Woodbridge, Ontario, in the business of construction.
6. Inspector Bell determined that the employer Creditview failed as an employer to ensure that the fall protection measures and procedures prescribed by section 26.1(2) of Ontario Regulation 213/91, were carried out at this construction project on November 1, 2014.

Sentencing Information:

Date of Sentence: September 16, 2016

Sentence (per count): \$5000 + 25% VFS

#### Section 4

#### **Fatality & Critical Injury Year-to-Date Overview - Construction Sector**

	<b>2016</b> 1st January – 31 <sup>st</sup> October 2016	<b>2015</b> 1 January – 31 Oct, 2015 comparison with same time period last
<b>Fatalities</b>	12	10
<b>Critical Injuries</b>	100	116

*\* NOTE: These figures represent preliminary data, and are not to be considered official statistics from the Ministry of Labour. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour.*

#### **REPORTING MONTHS: 1st – 31<sup>st</sup> October 2016 Monthly Summary Report**

#### **October 2016 Fatalities (2)**

*NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.*

By Sector	<ul style="list-style-type: none"> <li>• 2 –Apartment and other multiple housing</li> </ul>
Brief Summary  NOTE: These entries are in ascending date order (i.e. 1st to 31st) not sector order. See Section 5 for additional entry details.	<ul style="list-style-type: none"> <li>• Worker was struck by a bobcat</li> <li>• Worker was struck when a cinder block wall collapsed on them</li> </ul>

#### **October 2016 Critical Injuries (15)**

*NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.*

By Sector	<ul style="list-style-type: none"> <li>• 6 Single Family Housing</li> <li>• 2 Apartments and other multiple housing</li> <li>• 1 Highway and Road Construction</li> <li>• 1 Industrial Building Construction</li> <li>• 2 Institutional Building Construction</li> <li>• 1 Excavation &amp; Grading</li> <li>• 1 Well Drilling</li> <li>• 1 Commercial Building Construction</li> </ul>
Brief Summary	<ul style="list-style-type: none"> <li>• Worker's was climbing a vertical access ladder, slipped and fell</li> <li>• Worker moving a generator pinned their knee</li> <li>• Worker fell from a ladder approx. 8ft</li> <li>• Worker fell 20 ft. off roof</li> <li>• Worker fell through opening of floor to the basement</li> <li>• Worker was run over by a road machine when reversing</li> <li>• Worker slipped on concrete slab</li> <li>• Worker fell two storeys while roofing a residential home</li> <li>• Worker was doing waterproofing when the excavation wall collapsed on the worker.</li> <li>• Worker fell off roof</li> <li>• Worker hit by boom truck arm that snapped off</li> <li>• Worker found unconscious laying at bottom of stairs at a condo project</li> <li>• Worker fell from scaffold while doing masonry work</li> <li>• Worker fell from a scaffolding</li> <li>• Worker fell off roof</li> </ul>

**MOL Report to PLMHSC – Construction Sector – November 2016 Meeting**

**Section 5**

**Fatality & Critical Injury Year-to-Date Summaries\*- Construction Sector**

\*All new entries (current month and reconciled data) appear in **bold**.

NOTE: Some detail will inevitably be missing from the PLMHSC Report. The document is intended to provide an initial overview, not a comprehensive report. Annual data reporting approved by the Director should be used by stakeholders if they wish to see all data available to the Ministry related to an event.

**Fatalities Year-to-Date Summary (1 January to 31<sup>st</sup> October 2016): Total Year-to-**

**Date Fatalities: 12**

Note 1: Ages will be included when available.

Note 2: Reconciled data appears in bold

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
1	23 Mar 016	Eastern	tbd	Worker	Ice from an excavation wall fell on a worker.
2	10-May-16	Central	RESS	Worker	A worker suffered fatal injuries when he became caught between the guardrail of the elevated platform he was working on and the underside of a raised deck at the rear of a single family home under construction.
3	27-May-16	Central	RESM	Worker	Worker was shingling, fell off the roof and succumbed to his injuries.
4	10-June-16	Western	ROAD	Worker	Worker (driver) got out of the truck and didn't put the truck into parking mode and the truck backed up and pulled down a hydro line at the same time. Electrocuted.
5	17 June 16	Western	NECC	Worker	Worker was moving rocks and pinned by machinery against wall. Worker succumbed to his injuries 9 July 2016.
6	15-July-16	Western	NECC	Worker	Worker fell through metal sheet covering an opening through the roof. Worker succumbed to his injuries July 26, 2016.
7	09- August-16	Central West	ICI	Worker	Worker sustained fatal head injury while a scissor lift was in operation.
8	19 August-16	Central East	RESM	Worker	A worker doing restoration brick work on a building was fatally injured when the equipment he was using fell over.
9	24 August-16	Eastern	RESS	Worker	Worker was on a ladder, using a nail gun and received fatal wound to the chest.
10	9 Sept-16	Eastern	NECC	Worker	Worker was in a zoom boom bucket when the machine tipped over. Worker sustained fatal injuries.
11	<b>28 Oct 16</b>	<b>Central East</b>	<b>RESM</b>	<b>Worker</b>	<b>Worker was struck by a bobcat and succumbed to his injuries.</b>
12	<b>31 Oct 16</b>	<b>Central East</b>	<b>RESM</b>	<b>Worker</b>	<b>Worker was working on concrete stairs and cinder block wall when the wall collapsed on worker.</b>

**MOL Report to PLMHSC – Construction Sector – November 2016 Meeting**

**Critical Injuries Year-to-Date Summary (1 January to 31<sup>st</sup> October, 2016): Total Year-to-**

**Date Critical Injuries: 100**

Note 1: Ages will be included when available.

Note 2: Reconciled data appears in bold

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
1	05-Jan-16	Central East	INST	Worker	Worker fell 4 metres from scaffold, sustain broken leg.
2	09-Jan-16	Central East	INDU	Worker	Worker fell while installing new commercial oven chimney. Struck head – loss of consciousness
3	14-Jan-16	Central West	RESS	Worker	Worker fell 7 metres from scaffold, loss of consciousness & broken pelvis
4	18-Jan-16	Central East	RESS	Worker	Worker struck by material that fell of a truck, sustained broken leg.
5	20-Jan-16	Central East	RESM	Worker	Worker jumped from malfunctioning swing stage, sustained broken leg.
6	20-Jan-16	Western	COMM	Worker	Worker struck by material – loss of consciousness.
7	20-Jan-16	Eastern	RESM	Worker	Worker fell > 1 meter – broken leg and loss of consciousness.
8	21-Jan-16	Central West	RESS	Worker	Worker fell from ladder, broken leg.
9	28-Jan-16	Hamilton	BRID	Worker	Worker was wearing a full body harness, tied off with one lanyard to a fixed point at the time; worker walked further than he could with the lanyard, lost his balance and fell approx. 6 feet. Co-worker (health and safety rep) drove injured worker to Joseph Brant Hospital. IW had sustained a high ankle break.
10	04-Feb-16	Central West	ROAD	Worker	Caller alleges worker at this site (road work) was on top of a trailer pushing hot mix to the back of the trailer when he missed a step and fell to the ground; caller alleges he landed on his left arm; they drove him to Trillium Hospital where he was advised he fractured his arm.
11`	10-Feb-16	Central West	ROAD	Worker	Worker was struck by a vehicle and taken to the hospital. IW sustained a punctured lung and several broken ribs.
12	22-Feb-16	Western	RESS	Worker	Caller reports that a worker slipped on piece of plywood falling approx. 7 feet sustaining a broken leg.
13	27-Feb-16	Western	COMM	Worker	Worker broke his left heel & his right leg.
14	29-Feb-16	Eastern	RESM	Worker	Worker tripped on a wire, fell, and fractured arm.

**MOL Report to PLMHSC – Construction Sector – November 2016 Meeting**

15	29-Feb-16	Northern	ROAD	Worker	Worker was cutting a tree at this site when a branch fell and hit him on the head; loss of consciousness.
16	09-Mar-16	Central East	tbd	Worker	Worker was installing second floor joists. Worker struck in the eye with the nail from a nail gun. Permanent loss of sight to right eye.
17	10-Mar-16	Central West	INST	Worker	Worker hit head on ground; loss of consciousness; fractured arm.
18	14-Mar-16	Central East	COMM	Worker	Worker fell, landed on left elbow and left knee; suffered small fractures in each limb.
19	17-Mar-16	Western	tbd	Worker	Worker performing perimeter repairs on roof and fell losing consciousness
20	21-Mar-16	Western	tbd	Worker	Worker was on top of a core borer's anchor when it came loose and the machine hit him on the head; loss of consciousness.
21	22-Mar-16	Western	tbd	Worker	Drywall fell over on top of worker. Confirmed broken left tibia.
22	23-Mar-16	Central West	tbd	Worker	Worker fell 14 feet; broken leg.
23	26-Mar-16	Central East	COMM	Worker	Caller reports that a worker fell 15 ft. from a ladder; multiple injuries.
24	04-Apr-16	Eastern Region	RESS	Worker	Worker fell off a scaffold (approximately 7 ft.); arm injured.
25	05-Apr-16	Western Region	EXCA	Worker	Worker exiting truck while on jobsite was hit by passing pickup truck; multiple injuries.
26	11-Apr-16	Central East	RESM	Worker	A section of fly form slipped off the hydraulic jack while being lowered striking worker's leg; broken leg.
27	11-Apr-16	Western Region	INST	Worker	Worker tripped over exposed steel banding frozen in earth and fell; lost consciousness.
28	14-Apr-16	Northern	RESM	Worker	Worker was on a step ladder - found unconscious on ground; multiple injuries.
29	21-Apr-16	Central	INDU	Worker	Worker was on crane when it fell approx. 82 ft.; multiple injuries.
30	25-Apr-16	Eastern	ROAD	Worker	Worker struck by vehicle; multiple injuries.

MOL Report to PLMHSC – Construction Sector – November 2016 Meeting

31	03-May-16	Eastern	COMM	Worker	Worker was hanging a pipe on a step ladder and fell off. Worker suffered a broken arm.
32	05-May-16	Eastern	COMM	Worker	Worker on a construction site was smoothing out concrete and back over a little too much and fell over the edge. The worker fell off the edge and fell about 10 feet and suffered minor lacerations also lost consciousness.
33	09-May-16	Western	RESM	Worker	Worker was trapped under back hoe bucket and sustained a broken arm.
34	13-May-16	Central	RESM	Worker	Worker fell from the roof approx. 5 storeys. Worker suffered internal bleeding, one kidney removed, and damage to pancreas, liver and suffered fractures to elbow, pelvic bone and skull.
35	16-May-16	Eastern	COMM	Worker	Worker using hammer to hit a nail hammered his thumb and lost consciousness.
36	17-May-16	Central	NECC	Worker	Worker was doing painting work, when he fell off a ladder, hit head and lost consciousness.
37	18-May-16	Central	COMM	Worker	Worker fell off the roof because the scaffolding collapsed and suffered a broken collar bone.
38	18-May-16	Central	COMM	Worker	Worker fell off the roof because scaffolding collapsed and required stitches.
39	19-May 16	Eastern	RESS	Worker	Worker was working on a garage when a wall began to buckle and landed on him. Worker lost consciousness and suffered a concussion, pelvic, fracture, hip fracture and a small fracture to the vertebrae.
40	26-May 16	Eastern	RESS	Worker	Worker fell two storeys off a roof, lost consciousness and sustained a ruptured spleen.
41	6-June-16	Central	RESS	Worker	Due to not having his safety harness tied off, while decommissioning some industrial racks, the subcontractor fell 12 feet to the floor and suffered a broken arm.
42	7 June 16	Eastern	RESS	Worker	A young worker was working on a roof and fell. Fractured leg.
43	9 June 16	Western	NE	Worker	Worker passed out while constructing a deck and has sustained an unspecified injury to their back.
44	14 June 16	Central	EXCA	Worker	Worker working around excavated sewer approximately 6 feet deep lost footing slipped however did not fall the full distance down. Worker is said to have hurt elbow and scraped face but is said to have LOC.



MOL Report to PLMHSC – Construction Sector – November 2016 Meeting

45	20 June 16	Northern	MINP	Worker	Worker was injecting a two-part epoxy when the epoxy came in contact with worker's eyes and mouth and worker seemed fine and was sent to hospital via EMS. Hospital put worker in induced coma on a ventilator.
46	23 June 16	Central	NECC	Worker	A flag pole was being removed and the flag pole touch the wires above; live wire. The worker was holding the pole at the bottom and had an electrical shock
47	23 June 16	Western	PAVE	Worker	Worker was doing asphalt work in a parking lot near an asphalt cement tanker that has a heat transfer unit on it that keeps the asphalt warm. Worker went to climb on top of the truck to check up on it, a flame came up and burned the worker in the face. Worker was wearing a face shield, and that the face shield melted, resulting in burns to the face.
48	24 June 16	Western	RESS	Worker	Worker hit himself in the head with a hammer drill while fixing a lash machine. Worker suffered a loss of consciousness.
49	27 June 16	Eastern	INST	Worker	Worker was grabbing a set of windows from a stack when the stack fell on worker's leg. Broken leg
50	29 June 16	Eastern	COMM	Worker	Worker was going up a ladder but slipped and fell. Both arms broken.
51	5 July 16	Western	SEWW	Worker	A machine "flipped" over and hit a worker in the head causing the worker to lose consciousness
52	13 July 16	Central	INDU	Worker	Worker fractured pelvis from falling on beam.
53	14 July 16	Eastern	RAIL	Worker	Worker suffered an electrical shock- worker lost consciousness.
54	20 July 16	Eastern	ASB2	Worker	Worker fell off baker scaffold when a plank failed - worker sustained a fractured arm.
55	21 July 16	Northern	ROAD	Worker	Worker was welding a steel beam, the weld let go and the worker was hit by the beam when it fell. Broken leg.
56	26 July 16	Central	RESS	Worker	Worker fell 15' from a crank-up masonry scaffolding. Fractured arm.
57	30 July 16	Central West	RESS	Worker	Worker fractured ankle tripping over equipment
58	04 August 16	Eastern	COMM	Worker	The worker was cleaning a concrete pumping unit hopper when his hand got caught in the hopper blades severing his hand.
59	08 August 16	Eastern	RESM	Worker	Worker fell approx. 30 ft. when the scaffold system collapsed. Worker sustained fractures to both legs and back injuries.

MOL Report to PLMHSC – Construction Sector – November 2016 Meeting

60	15 August 16	Central East	INDU	Worker	Worker moving dirt with a mini excavator, backed it up and caught his leg between the machine and curb. Worker sustained a broken leg.
61	15 August 16	Central West	PAVE	Worker	Worker struck by tongue of equipment trailer when tipped up; worker sustained fractured left arm.
62	18 August 16	Western	RESM	Worker	Worker sustained a fracture to the upper ulna bone in left arm after falling approximately 4 ft. off a ladder.
63	18 August 16	Central East	INST	Worker	Worker tripped and fell on a piece of rebar. Worker sustained a broken right forearm.
64	19 August 16	Central West	NECC	Worker	Worker was on a ladder and fell 12 feet. Worker fractured left knee
65	19 August 16	Northern	RESS	Worker	Two men fell off scaffolding working on house. One worker was unconscious upon falling
66	24 August 16	Central West	RESS	Worker	Worker was on while constructing a temporary work platform which collapsed. Worker fractured right leg
67	28 August 16	Western	COMM	Worker	Worker was pulling material during a demolition fell backwards, hit his head on the concrete floor and was unconscious
68	29 August 16	Western	RESS	Worker	Worker fell off ladder and suffered head trauma while roofing
69	01 Sept 16	Eastern	ROAD	Worker	Worker's leg was run over by a bulldozer that was backfilling
70	01 Sept 16	Central East	SEWW	Worker	Workers lost consciousness after being hit by fence blown over by wind
71	01 Sept 16	Western	RESM	Worker	Worker fell 24 ft. from a scaffold and sustained severe head injuries
72	02 Sept 16	Eastern	RESS	Worker	Worker fell 20 ft. onto a lower second roof while roofing single family home
73	02 Sept 16	Central-West	RESS	Worker	Worker operating bobcat when it tipped over trapping him
74	07 Sept 16	Central- East	RESM	Worker	Worker was injured when he fell from a height of 8.6 ft. during installation of form-work decking.
75	09 Sept 16	Central-West	NECC	Worker	Worker was struck in the leg by the bucket of an excavator
76	14 Sept 16	Northern	RESS	Worker	Worker fell from ladder striking head resulting in loss of consciousness
77	14 Sept 16	Central-West	SEWW	Worker	Worker was using a cut off saw to cut wood, the saw "jumped up" at him and hit the worker in the right arm pit

MOL Report to PLMHSC – Construction Sector – November 2016 Meeting

78	15 Sept 16	Central-West	ROAD	Worker	Worker was struck by a vehicle when he was opening a lane of traffic on 403
79	15 Sept 16	Central-East	RESM	Worker	Worker who was on a ladder leaning against a 53 foot trailer fell with the ladder to the ground. Worker is said to have sustained unspecified injuries to the right hip and arm
80	20 Sept 16	Central-West	RESS	Worker	Worker fell from ladder 13 feet through wooden safety fence, fractured right hip and femur
81	21 Sept 16	Eastern	RESS	Worker	Worker fell off a ladder while installing siding, suffered a fractured leg.
82	26 Sept 16	West	ROAD	Worker	Worker burned by tar spill in back of truck
83	26 Sept 16	Central East	NECC	Worker	Worker climbing to the mezzanine/mechanical room fell from ladder falling onto cement floor
84	26 Sept 16	Central East	INDU	Worker	<b>Worker was climbing a vertical access ladder, slipped and fell</b>
85	27 Sept 16	West	NECC	Worker	Worker was refilling a three inch gas water pump when the front side of his body caught on fire
86	27 Sept 16	Central West	INST	Worker	Worker had a stack of doors fall on them when unloading from a truck.
87	29 Sept 16	Eastern	INST	Worker	<b>Worker was moving a generator, generator shifted &amp; pinned workers knee, fractured right leg</b>
88	03 Oct 16	Eastern	RESS	Worker	<b>Worker fell off a ladder approx. 8ft. hitting head on concrete floor suffering unconsciousness.</b>
89	04 Oct 16	Central West	RESS	Worker	<b>Worker fell 20 ft. off a roof, sustained cracked skull and a broken vertebrae</b>
90	04 Oct 16	West	WELL	Worker	<b>Worker was struck on the head by a boom truck arm snapping off during the lifting a pellet of cement bags</b>
91	05 Oct 16	Central West	RESS	Worker	<b>Worker on a renovation project fell through the floor to the basement. Sustained fracture to skull and collarbone</b>
92	05 Oct 16	West	ROAD	Worker	<b>Worker suffered critical injuries when a road machine reversed and ran worker over</b>
93	07 Oct 16	Central West	RESS	Worker	<b>Worker fell off residential roof.</b>
94	12 Oct 16	West	RESM	Worker	<b>Worker was found unconscious laying at the bottom of the stairs, worker regained consciousness</b>
95	17 Oct 16	Central East	INST	Worker	<b>Worker slipped on concrete slab</b>

MOL Report to PLMHSC – Construction Sector – November 2016 Meeting

96	21 Oct 16	Eastern	RESS	Worker	Worker fell two storeys off the roof of a home, in and out of consciousness
97	22 Oct 16	West	COMM	Worker	Worker was on scaffolding applying masonry work to plaza and fell approx 20 feet through the scaffolding
98	24 Oct 16	Central West	RESM	Worker	Worker fell 16 feet when scaffolding collapsed. Worker sustained head and back injuries and suffered a loss of consciousness.
99	25 Oct 16	Central East	GRAD	Worker	Worker was doing waterproofing in an excavation. The east wall collapsed onto the worker. Worker sustained a fractured hip
100	26 Oct 16	Central East	RESS	Worker	Worker was working on a roof when he fell 6.3 m to the ground below and suffered a broken right leg and possible head injury