Reporting Month Statistics – Quick Overview

Reporting Month	Month Fatalities	Month Critical Injuries	Month Total
November 2016	1	25	26

Provincial Coordinators Comment: December 2016

Firstly I would like to thank everyone for their support over the last eight weeks as I have been getting my feet wet and finding my way. It has been a real pleasure meeting and getting to know everyone and working alongside each and every one of you for the same common goal; reduce and eliminate the number of workplace fatalities that we have in our workplaces in the province. I hope that someday we will be able to report on just that, all workers in the province when working on construction projects went home safe this year....and next.

We are currently focusing on getting ready with the suspended access equipment legislation that comes into force January 1st, 2017. We have been working closely with industry to ensure that their concerns have been heard and taken into account. IHSA is continuing to work on their worker and supervisor training programs as the MOL develops a technical guidance document for industry.

My specialists are involved with the MOL's sector plan, preparing for next year. I have been travelling around the province discussing and reviewing the high hazards that our inspectors are witnessing from the previous year and discussing where our priorities and focus should be on for next year.

A very interesting case that occurred in the Bayfield area out of the London District (Case #4 attached). This case involved a roofing company in which a fall from heights occurred. The owner of the company instructed a worker to alter the scene by installing proper anchor points and life lines, thus trying to throw off the investigation. The owner was found guilty and the Justice stated "The obstruction in this case shows dishonesty. Her Worship stated that this type of conduct is as close as it gets to criminal conduct in Occupational Health and Safety matters and that a short, sharp custodial sentence was appropriate." A three day custodial sentence was imposed. The Ministry will be seeking more penalties when it comes to these types of infractions moving forward.

I look forward to working with each and every one of you during my assignment as Provincial Coordinator to try and move the health and safety system of Ontario forward.

I wish each of you a very happy and safe holiday season and look forward to working with you in 2017.

Sincerely,

Chris Plouffe

(A) Provincial Coordinator Construction Health and Safety, Ministry of Labour

MOL Current Events

- Electrical Hazard Fact Sheet (Nov 2016)
 https://www.labour.gov.on.ca/english/hs/sawo/pubs/fs_electrical.php
- Ontario Increases Minimum Wage (Oct 2016) https://www.labour.gov.on.ca/english/es/pubs/guide/minwage.php
- Workplace Violence and Harassment Code of Practice (effective Sept 8, 2016) https://www.labour.gov.on.ca/english/hs/pubs/harassment/index.php
- 2016-2017 Inspection Blitzes and Initiatives http://www.labour.gov.on.ca/english/resources/blitzschedule.php
- Safe At Work Ontario Annual Report Results for April 2014 March 2015 (20 April 2016) http://www.labour.gov.on.ca/english/hs/sawo/report/index.php
- Small Business Health and Safety Checklist http://www.forms.ssb.gov.on.ca/mbs/ssb/forms/ssbforms.nsf/FormDetail?OpenForm&ACT=RDR&TAB=PROFILE&SRC H=1&ENV=WWE&TIT=1960&NO=1960E
- Working at Heights Training (content reviewed March 2016)
 http://www.labour.gov.on.ca/english/hs/topics/heights.php?utm_source=molwebsite&utm_medium=banner&utm_content=s
 potlighths_EN&utm_campaign=WorkingAtHeights
- Occupational Exposure Limits http://www.labour.gov.on.ca/english/about/consultations/oels/index.php
- Replacing Your Roof (content reviewed March 2016)
 http://www.labour.gov.on.ca/english/resources/roofing.php?utm_source=molwebsite&utm_medium=banner&utm_content=s
 potlighths_EN&utm_campaign=RoofingPilot
- Alert: Elevating Work Platform Crushing Hazard (April 2016) http://www.labour.gov.on.ca/english/hs/pubs/alerts/a36.php

CASE 1

Def: Vic Priestly Contracting Limited

Vic Priestly Contracting Limited, 3200 Lloydtown Aurora Road, King, Ontario, L7B 0G3, on or about the 8th day of December, 2014, in the City of Ottawa, in the East Region, in the Province of Ontario, did commit the offence of failing as an employer to ensure that the equipment, materials and protective devices provided by the employer were maintained in good condition at a project located at or near the Riverside staging area on the Vanier Parkway off ramp heading west from the north side, northeast of the Hurdman Bridge, Ottawa, Ontario, contrary to s. 25(1)(b) of the Occupational Health and Safety Act, R.S.O. 1990, c.O.1.

Particulars: The Defendant failed to maintain the trailer in good condition.

Conviction Information

Date(s) of Trial/Plea: June 24, 2016

Date of Disposition: June 24, 2016

Name of Judge/JP: Her Worship Ana Costa

Court Location: Toronto Provincial Offences Court

70 Center Avenue,

Toronto, ON

Facts in Support of Guilty Plea:

- [1] Vic Priestly Contracting Limited ("VPCL") is a corporation incorporated pursuant to the laws of Ontario. At all material times, VPCL was an employer as defined by the Occupational Health and Safety Act, R.S.O. 1990, Chapter O.1 (the "Act").
- [2] The offence, which is detailed below, occurred at or near the Riverside staging area on the Vanier Parkway off ramp, heading west from the north side, northeast of the Hurdman bridge, Ottawa, Ontario which was, at all material times, a project ("project") as defined by the Act.
- [3] On December 8, 2014, the Ottawa Light Rail Transit Constructors was the constructor of the project where light rail transit was being built. VPCL was subcontracted to move heavy equipment from the project. A float driver, employed by VPCL, entered the project to hook a mobile office trailer to a tractor trailer for transportation. He was assisted by a worker ("worker") employed by another company present at the project. Due to the trailer coupler latch mechanism being damaged, the tongue on the trailer fell on the worker's foot during the hook-up process. The worker sustained a crushing injury requiring him to have the four small toes on his left foot removed.
- [4] As such, VPCL committed the offence of failing, as an employer, to ensure that the trailer was maintained in good condition at the project contrary to section 25(1)(b) of the Act.

Sentencing Information:

Date of Sentence: June 24, 2016

Sentence: \$45,000 + VFS

CASE 2

Def: Luis Tavares Director of <u>Utility Force Inc.</u> and Supervisor as per OHSA

Luis Tavares, 1623 Ogden Avenue, Mississauga, Ontario L5E 2J2, on or about the 12th day of May, 2015 at the City of Toronto, in the Toronto Region, did commit the offence of failing, as a supervisor, to ensure that workers worked in the manner and with the measures and procedures required by section 234(1) of Ontario Regulation 213/91, contrary to section 27(1)(a) of the Occupational Health and Safety Act, R.S.O. 1990, c. O.1, as amended.

<u>Particulars</u>: The accused failed to ensure that Helio Tavares and/or Helio Picanco did not enter an unshored and unsloped trench.

Conviction Information

Date(s) of Trial / Plea: October 7, 2016 Date of Disposition: October 7, 2016

Name of Judge/JP: Justice of the Peace Edwards

Court Location: Ontario Court of Justice

70 Centre Ave Toronto, Ontario

Facts in Support of Guilty Plea

Utility Force Inc. is an Ontario corporation, engaged in the business of installing and connecting water and sewage lines between municipal main lines and residential sites. Luis Tavares is a director of the corporation and is a "supervisor" as defined in the Occupational Health and Safety Act ("OHSA").

On May 12, 2015 a Utility Force crew was installing water and sewage lines at new residential premises located at 341 and 345 Albion Road in the City of Toronto. This was a "project" as defined in the OHSA, and so the provisions of the Construction Regulation (O. Reg. 213/91) were applicable.

On that date a Ministry of Labour inspector attended at the site for a proactive inspection. On arrival, he observed two individuals inside a trench. The individuals were identified as employees of Utility Force Inc., and were "workers" as defined in the OHSA. The trench was measured to be 2.17 metres deep. Its sides were not sloped, and no shoring support equipment was installed as required by section 234(1) of the Construction Regulation. A ladder had been placed in the trench for access and egress.

On site at the time were two 4' x 8' "speed shoring" units and an 8' x 8' aluminum shoring box. Speed shoring involves the use of 4' x 8' plywood sheets held apart and in place by hydraulic means. Earlier in the day the two speed shoring units had been damaged. At the time the Ministry of Labour inspector observed the two workers in the trench, Mr. Tavares and the crew foreman were in the process of repairing the speed shoring that was located in front of the trench at 345 Albion Road. The workers entered the trench on their own initiative. Neither Mr. Tavares nor the crew foreman ordered the workers out of the unsupported trench.

Sentencing Information:

Date of Sentence: October 7, 2016 Sentence: \$5000 + VFS

CASE 3

Def: LOVERA-HOMES INC.

Lovera-Homes Inc., 1566 Stoney Brook Trail, Oakville, Ontario, L6M 2R6, on or about the 6th day of July 2015, at the City of Toronto in the Toronto Region of the Province of Ontario, did commit the offence of failing, as an employer, to ensure that the measures and procedures prescribed by section 109 of Ontario Regulation 213/91, as amended, were carried out at a project located at or near 33 Cavendish Street in Toronto, Ontario, contrary to section 25(1)(c) of the Occupational Health and Safety Act, R.S.O. 1990, c. O.1, as amended.

Conviction Information

Date(s) of Trial / Plea: September 8, 2016

Date of Disposition: September 8, 2016

Name of Judge/JP: His Worship Sunit John

Court Location: Ontario Court of Justice

70 Centre Ave. Toronto, ON

Facts in Support of Guilty Plea:

1. Lovera-Homes Inc. ("the defendant") was at all material times an "employer" as defined by the *Occupational Health and Safety Act* and a corporation duly registered pursuant to the laws of the Province of Ontario. Jorge Lovera is the owner and sole-director of Lovera-Homes Inc.

- 2. The defendant contracted to renovate the second story washroom within a single family dwelling located at 33 Cavendish Street in Toronto.
- 3. On Monday July 6, 2015, Mr. Lovera and an employee of Lovera-Homes Inc. arrived at the project to carry out renovation work. The employee was cutting strips of plywood using a table saw that was set up in the driveway area of the dwelling when his right hand slipped and made contact with the cutting blade. The saw did not have a guard in to protect the worker from the blade. Mr. Lovera, who was working in the second level washroom area, heard the worker's calls for help and immediately rushed to assist.
- 4. The worker was transported to hospital for treatment. The worker's right index finger was severed at the metacarpophalangeal joint (the knuckle between the hand and the finger) and his right thumb was partially severed.
- 5. On July 6, 2015, Lovera-Homes Inc. failed, as an employer, to ensure that the measures and procedures prescribed by section 109 of *Ontario Regulation 213/91* were carried out at a project located at 33 Cavendish Street, Toronto, contrary to section 25(1)(c) of the *Occupational Health and Safety Act*.

Sentencing Information:

Date of Sentence: September 8, 2016 Sentence: \$10, 500 + VFS

CASE 4

Def: A Bradley Clothier, carrying on business as AB Clothier Roofing

A Bradley Clothier, carrying on business as AB Clothier Roofing, 57 Charles St., Dorchester, ON, N0L 1G0, on or about the 17th day of August 2015, in the Municipality of Bluewater, in the Southwest Region of the Province of Ontario, did commit the offence of failing, as an employer, to ensure that measures and procedures prescribed by section 26.1(2) of Ontario Regulation 213/91, as amended, were carried out at a workplace located at 49 Bayfield Terrace, Bayfield, Ontario, contrary to section 25(1)(c) of the Occupational Health and Safety Act, R.S.O. 1990, c. O.1, as amended.

Particulars: The defendant failed to ensure that a worker was adequately protected by a method of fall protection.

3. AND FURTHER THAT, A Bradley Clothier, carrying on business as AB Clothier Roofing, 57 Charles St., Dorchester, ON, N0L 1G0, on or about the 17th day of August 2015, in the Municipality of Bluewater, in the Southwest Region of the Province of Ontario, did commit the offence of hindering, obstructing, molesting or interfering, or attempting to hinder, obstruct, molest, or interfere with an inspector, in the exercise of his power, or performance of a duty, under section 54 of the Occupational Health and Safety Act, R.S.O. 1990, c.O.1, as amended, contrary to s.62(1) of that Act.

Conviction Information

Date(s) of Trial / Plea: November 3, 2016

Date of Disposition: November 3, 2016

Name of Judge/JP: Her Worship Hampson

Court Location: Ontario Court of Justice

1 Court House Square Goderich, Ontario

Facts in Support of Guilty Plea:

- 1. The Defendant, A. Bradley Clothier operates a roofing business as a sole proprietor called AB Clothier Roofing.
- 2. On August 17, 2015, three workers for AB Clothier Roofing, including Mr. Clothier himself were working on a residential roofing project at a two storey home in the town of Bayfield.
- 3. Mr. Clothier did not make fall protection available for the workers on the project.
- 4. One worker fell from the roof a distance of 18 feet and broke his jaw, left arm and right leg in the fall.

5. After the worker fell, Mr. Clothier directed the third worker at the site to go up onto the roof and put up lifelines and fall protection equipment in an attempt to deceive the Ministry of Labour investigation that would take place.

Sentencing Information:

Date of Sentence: November 3, 2016

\$5,000 + VFS fine imposed on count 1

3 day custodial sentence on count 3 - The obstruction in this case shows dishonesty. Her Worship opined that this type of conduct is as close as it gets to criminal conduct in Occupational Health and Safety matters and that a short, sharp custodial sentence was appropriate.

Fatality & Critical Injury Year-to-Date Overview - Construction Sector

	2016 1st January – 30 st November 2016	2015 1 January – 30 th November, 2015
Fatalities	13	15
Critical Injuries		
	125	127

^{*} NOTE: These figures represent preliminary data, and are not to be considered official statistics from the Ministry of Labour. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour.

REPORTING MONTHS: 1st – 30st November 2016 Monthly Summary Report

November 2016 Fatalities (1)

NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.

By Sector	• 1 Hydro
Brief Summary	Worker installing a new electrical on roof fell through skylight
NOTE: These entries are in ascending date order (i.e. 1st to 31st) not sector order. See Section 5 for additional entry details.	

November 2016 Critical Injuries (25)

NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry's data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.

By Sector 8 Single Family Housing 6 Commercial Building Construction 2 Apartments and other multiple housing 2 Highway and Road Construction 1 Institutional Building Construction 1 Institutional Building Construction 1 Institutional Building Construction 1 Excavation & Grading 1 Hydroelectric Power Plants and Related 1 Sewer/Watermain Construction 1 Construction Brief Summary Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker floss consciousness Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was struck by hoist crane Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fll 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker tripped over cable Worker fell from 11/2 stories roof Worker lost heart attack at the construction site Worker lost footing fell into basement Worker fell on worker fell on worker Worker lost footing fell into basement Worker fell on worker fell on worker Worker lost footing fell into basement Worker fell of framp and fractured arm		
2 Apartments and other multiple housing 2 Highway and Road Construction 2 Industrial Building Construction 1 Institutional Building Construction 1 Excavation & Grading 1 Hydroelectric Power Plants and Related 1 Sewer/Watermain Construction 1 Construction Brief Summary Worker installing plywood around a column, slipped & fell Worker hit by falling rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fiell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker loss consciousness Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker sustained an injury to his foot Worker was struck by hoist crane Worker was struck by hoist crane Worker was struck in the head while stripping concrete Worker fiell through roof opening Worker was struck in the head while stripping concrete Worker fripped and fell while walking down a depression Worker fripped over cable Worker was installing electrical conduit, tripped and fell Worker was installing electrical conduit, tripped and fell Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker fost footing fell into basement Worker fell off ramp and fractured arm	By Sector	8 Single Family Housing
2 Highway and Road Construction 2 Industrial Building Construction 1 Institutional Building Construction 1 Institutional Building Construction 1 Excavation & Grading 1 Hydroelectric Power Plants and Related 1 Sewer/Watermain Construction 1 Construction Brief Summary Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker fill from roof onto parking garage Worker fell from roof onto parking garage Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker sustained an injury to his foot Worker was struck by hoist crane Worker was struck by hoist crane Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker fell 10 ft in a parking garage and fractured elbow Worker tripped and fell while walking down a depression Worker fell and broke ankle while entering the cab of his crane Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker took heart attack at the construction broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm		6 Commercial Building Construction
2 Industrial Building Construction 1 Institutional Building Construction 1 Excavation & Grading 1 Hydroelectric Power Plants and Related 1 Sewer/Watermain Construction 1 Construction Brief Summary Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker was struck by hoist crane Worker fell through roof opening Worker tripped and fell while walking down a depression Worker tripped over cable Worker tripped over cable Worker fill and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker lost footing fell into basement Worker lost footing fell into basement Worker lost footing fell into basement Worker fell of framp and fractured arm		• 2 Apartments and other multiple housing
Institutional Building Construction I Excavation & Grading I Hydroelectric Power Plants and Related I Sewer/Watermain Construction I Construction Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker foss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker fell and broke ankle while entering the cab of his crane Worker fell and broke ankle while entering the cab of his crane Worker took heart attack at the construction site Worker took heart attack at the construction broke, fell on worker Worker lost footing framed glass, upper section broke, fell on worker Worker fell off ramp and fractured arm		2 Highway and Road Construction
I Excavation & Grading I Hydroelectric Power Plants and Related I Sewer/Watermain Construction I Construction Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped over cable Worker fell 10 ft in a parking garage and fractured elbow Worker was installing electrical conduit, tripped and fell Worker was installing electrical conduit, tripped and fell Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm		2 Industrial Building Construction
I Hydroelectric Power Plants and Related I Sewer/Watermain Construction I Construction Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker frestured foot when panel being hoisted up fell on foot Worker loss consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker was struck by hoist crane Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell and broke ankle while entering the cab of his crane Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm		1 Institutional Building Construction
Brief Summary • 1 Sewer/Watermain Construction • 1 Construction • Worker installing plywood around a column, slipped & fell • Worker moving rebar from backhoe fell • Worker hit by falling rebar dowel on the head • Worker fell from roof onto parking garage • Worker was moving a truss on the roof, missed step, fell 10 ft • Worker fractured foot when panel being hoisted up fell on foot • Worker foll from scaffold; lost consciousness • Worker fell from scaffold; lost consciousness • Worker sustained an injury to his foot • Worker was building commercial building and cut arm on saw • Worker was struck by hoist crane • Worker fell through roof opening • Worker was struck in the head while stripping concrete • Worker tripped and fell while walking down a depression • Worker fell 10 ft in a parking garage and fractured elbow • Worker tripped over cable • Worker was installing electrical conduit, tripped and fell • Worker fell and broke ankle while entering the cab of his crane • Worker fell from 11/2 stories roof • Worker took heart attack at the construction site • Worker was moving framed glass, upper section broke, fell on worker • Worker lost footing fell into basement • Worker fell off ramp and fractured arm		1 Excavation & Grading
Brief Summary • Worker installing plywood around a column, slipped & fell • Worker moving rebar from backhoe fell • Worker hit by falling rebar dowel on the head • Worker fell from roof onto parking garage • Worker was moving a truss on the roof, missed step, fell 10 ft • Worker fractured foot when panel being hoisted up fell on foot • Worker loss consciousness • Worker fell from scaffold; lost consciousness • Worker sustained an injury to his foot • Worker was building commercial building and cut arm on saw • Worker was struck by hoist crane • Worker fell through roof opening • Worker was struck in the head while stripping concrete • Worker tripped and fell while walking down a depression • Worker fell 10 ft in a parking garage and fractured elbow • Worker tripped over cable • Worker was installing electrical conduit, tripped and fell • Worker fell and broke ankle while entering the cab of his crane • Worker fell from 11/2 stories roof • Worker took heart attack at the construction site • Worker was moving framed glass, upper section broke, fell on worker • Worker lost footing fell into basement • Worker fell off ramp and fractured arm		1 Hydroelectric Power Plants and Related
Brief Summary Worker installing plywood around a column, slipped & fell Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker lost footing fell into basement Worker fell off ramp and fractured arm		1 Sewer/Watermain Construction
 Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		• 1 Construction
 Worker moving rebar from backhoe fell Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Western's setabline above all according allowed 9 fell
 Worker hit by falling rebar dowel on the head Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 	Brief Summary	**
 Worker fell from roof onto parking garage Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker foll from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker was moving a truss on the roof, missed step, fell 10 ft Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker fell off ramp and fractured arm 		
 Worker fractured foot when panel being hoisted up fell on foot Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker loss consciousness Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker fell from scaffold; lost consciousness Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker sustained an injury to his foot Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker was building commercial building and cut arm on saw Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker was struck by hoist crane Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker fell through roof opening Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker was struck in the head while stripping concrete Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker tripped and fell while walking down a depression Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		
 Worker fell 10 ft in a parking garage and fractured elbow Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker was struck in the head while stripping concrete
 Worker tripped over cable Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker tripped and fell while walking down a depression
 Worker was installing electrical conduit, tripped and fell Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker fell 10 ft in a parking garage and fractured elbow
 Worker fell and broke ankle while entering the cab of his crane Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker tripped over cable
 Worker fell from 11/2 stories roof Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker was installing electrical conduit, tripped and fell
 Worker took heart attack at the construction site Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		 Worker fell and broke ankle while entering the cab of his crane
 Worker was moving framed glass, upper section broke, fell on worker Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker fell from 11/2 stories roof
 Worker lost footing fell into basement Worker fell off ramp and fractured arm 		Worker took heart attack at the construction site
Worker fell off ramp and fractured arm		 Worker was moving framed glass, upper section broke, fell on worker
		Worker lost footing fell into basement
		Worker fell off ramp and fractured arm
 Worker fell off formwork and hit head 		Worker fell off formwork and hit head
Worker while acting as a spotter was struck by elevated work platform		Worker while acting as a spotter was struck by elevated work platform

Fatality & Critical Injury Year-to-Date Summaries*- Construction Sector

*All new entries (current month and reconciled data) appear in **bold**.

NOTE: Some detail will inevitably be missing from the PLMHSC Report. The document is intended to provide an initial overview, not a comprehensive report. Annual data reporting approved by the Director should be used by stakeholders if they wish to see all data available to the Ministry related to an event.

Fatalities Year-to-Date Summary (1 January to 30th November,

2016):

Total Year-to-Date Fatalities: 13

Note 1: Ages will be included when available. Note

2: Reconciled data appears in bold

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
1	23 Mar 016	Eastern	tbd	Worker	Ice from an excavation wall fell on a worker.
2	10-May-16	Central	RESS	Worker	A worker suffered fatal injuries when he became caught between the guardrail of the elevated platform he was working on and the underside of a raised deck at the rear of a single family home under construction.
3	27-May-16	Central	RESM	Worker	Worker was shingling, fell off the roof and succumbed to his injuries.
4	10-June-16	Western	ROAD	Worker	Worker (driver) got out of the truck and didn't put the truck into parking mode and the truck backed up and pulled down a hydro line at the same time. Electrocuted.
5	17 June 16	Western	NECC	Worker	Worker was moving rocks and pinned by machinery against wall. Worker succumbed to his injuries 9 July 2016.
6	15-July-16	Western	NECC	Worker	Worker fell through metal sheet covering an opening through the roof. Worker succumbed to his injuries July 26, 2016.
7	09- August-16	Central West	ICI	Worker	Worker sustained fatal head injury while a scissor lift was in operation.
8	19 August-16	Central East	RESM	Worker	A worker doing restoration brick work on a building was fatally injured when the equipment he was using fell over.
9	24 August-16	Eastern	RESS	Worker	Worker was on a ladder, using a nail gun and received fatal wound to the chest.
10	9 Sept-16	Eastern	NECC	Worker	Worker was in a zoom boom bucket when the machine tipped over. Worker sustained fatal injuries.

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
11	28 Oct 16	Central East	RESM	Worker	Worker was struck by a bobcat and succumbed to his injuries.
12	31 Oct 16	Central East	RESM	Worker	Worker was working on concrete stairs and cinder block wall when the wall collapsed on worker.
13	03-Nov-16	West	INDU	Worker	Worker was installing new electrical service on roof, worker tripped and fell through skylight landing on the floor below.

Critical Injuries Year-to-Date Summary (1 January to 30th November,

2016): Total Year-to-Date Critical Injuries: 125

Note 1: Ages will be included when available. Note

2: Reconciled data appears in bold

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
1	05-Jan-16	Central East	INST	Worker	Worker fell 4 metres from scaffold, sustain broken leg.
2	09-Jan-16	Central East	INDU	Worker	Worker fell while installing new commercial oven chimney. Struck head – loss of consciousness
3	14-Jan-16	Central West	RESS	Worker	Worker fell 7 metres from scaffold, loss of consciousness & broken pelvis
4	18-Jan-16	Central East	RESS	Worker	Worker struck by material that fell of a truck, sustained broken leg.
5	20-Jan-16	Central East	RESM	Worker	Worker jumped from malfunctioning swing stage, sustained broken leg.
6	20-Jan-16	Western	COMM	Worker	Worker struck by material – loss of consciousness.
7	20-Jan-16	Eastern	RESM	Worker	Worker fell > 1 meter – broken leg and loss of consciousness.
8	21-Jan-16	Central West	RESS	Worker	Worker fell from ladder, broken leg.
9	28-Jan-16	Hamilton	BRID	Worker	Worker was wearing a full body harness, tied off with one lanyard to a fixed point at the time; worker walked further than he could with the lanyard, lost his balance and fell approx. 6 feet. Co-worker (health and safety rep) drove injured worker to Joseph Brant Hospital. IW had sustained a high ankle break.
10	04-Feb-16	Central West	ROAD	Worker	Caller alleges worker at this site (road work) was on top of a trailer pushing hot mix to the back of the trailer when he missed a step and fell to the ground; caller alleges he landed on his left arm; they drove him to Trillium Hospital where he was advised he fractured his arm.
11`	10-Feb-16	Central West	ROAD	Worker	Worker was struck by a vehicle and taken to the hospital. IW sustained a punctured lung and several broken ribs.
12	22-Feb-16	Western	RESS	Worker	Caller reports that a worker slipped on piece of plywood falling approx. 7 feet sustaining a broken leg.
13	27-Feb-16	Western	COMM	Worker	Worker broke his left heel & his right leg.
14	29-Feb-16	Eastern	RESM	Worker	Worker tripped on a wire, fell, and fractured arm.

	T	T			
15	29-Feb-16	Northern	ROAD	Worker	Worker was cutting a tree at this site when a branch fell and hit him on the head; loss of consciousness.
16	09-Mar-16	Central East	tbd	Worker	Worker was installing second floor joists. Worker struck in the eye with the nail from a nail gun. Permanent loss of sight to right eye.
17	10-Mar-16	Central West	INST	Worker	Worker hit head on ground; loss of consciousness; fractured arm.
18	14-Mar-16	Central East	COMM	Worker	Worker fell, landed on left elbow and left knee; suffered small fractures in each limb.
19	17-Mar-16	Western	tbd	Worker	Worker performing perimeter repairs on roof and fell losing consciousness
20	21-Mar-16	Western	tbd	Worker	Worker was on top of a core borer's anchor when it came loose and the machine hit him on the head; loss of consciousness.
21	22-Mar-16	Western	tbd	Worker	Drywall fell over on top of worker. Confirmed broken left tibia.
22	23-Mar-16	Central West	tbd	Worker	Worker fell 14 feet; broken leg.
23	26-Mar-16	Central East	COMM	Worker	Caller reports that a worker fell 15 ft. from a ladder; multiple injuries.
24	04-Apr-16	Eastern Region	RESS	Worker	Worker fell off a scaffold (approximately 7 ft.); arm injured.
25	05-Apr-16	Western Region	EXCA	Worker	Worker exiting truck while on jobsite was hit by passing pickup truck; multiple injuries.
26	11-Apr-16	Central East	RESM	Worker	A section of fly form slipped off the hydraulic jack while being lowered striking worker's leg; broken leg.
27	11-Apr-16	Western Region	INST	Worker	Worker tripped over exposed steel banding frozen in earth and fell; lost consciousness.
28	14-Apr-16	Northern	RESM	Worker	Worker was on a step ladder - found unconscious on ground; multiple injuries.
29	21-Apr-16	Central	INDU	Worker	Worker was on crane when it fell approx. 82 ft.; multiple injuries.
30	25-Apr-16	Eastern	ROAD	Worker	Worker struck by vehicle; multiple injuries.

31	03-May-16	Eastern	COMM	Worker	Worker was hanging a pipe on a step ladder and fell off. Worker suffered a broken arm.
32	05-May-16	Eastern	COMM	Worker	Worker on a construction site was smoothing out concrete and back over a little too much and fell over the edge. The worker fell off the edge and fell about 10 feet and suffered minor lacerations also lost consciousness.
33	09-May-16	Western	RESM	Worker	Worker was trapped under back hoe bucket and sustained a broken arm.
34	13-May-16	Central	RESM	Worker	Worker fell from the roof approx. 5 storeys. Worker suffered internal bleeding, one kidney removed, and damage to pancreas, liver and suffered fractures to elbow, pelvic bone and skull.
35	16-May-16	Eastern	COMM	Worker	Worker using hammer to hit a nail hammered his thumb and lost consciousness.
36	17-May-16	Central	NECC	Worker	Worker was doing painting work, when he fell off a ladder, hit head and lost consciousness.
37	18-May-16	Central	COMM	Worker	Worker fell off the roof because the scaffolding collapsed and suffered a broken collar bone.
38	18-May-16	Central	COMM	Worker	Worker fell off the roof because scaffolding collapsed and required stitches.
39	19-May 16	Eastern	RESS	Worker	Worker was working on a garage when a wall began to buckle and landed on him. Worker lost consciousness and suffered a concussion, pelvic, fracture, hip fracture and a small fracture to the vertebrae.
40	26-May 16	Eastern	RESS	Worker	Worker fell two storeys off a roof, lost consciousness and sustained a ruptured spleen.
41	6-June-16	Central	RESS	Worker	Due to not having his safety harness tied off, while decommissioning some industrial racks, the subcontractor fell 12 feet to the floor and suffered a broken arm.
42	7 June 16	Eastern	RESS	Worker	A young worker was working on a roof and fell. Fractured leg.
43	9 June 16	Western	NE	Worker	Worker passed out while constructing a deck and has sustained an unspecified injury to their back.
44	14 June 16	Central	EXCA	Worker	Worker working around excavated sewer approximately 6 feet deep lost footing slipped however did not fall the full distance down. Worker is said to have hurt elbow and scraped face but is said to have LOC.

	_				
45	20 June 16	Northern	MINP	Worker	Worker was injecting a two-part epoxy when the epoxy came in contact with worker's eyes and mouth and worker seemed fine and was sent to hospital via EMS. Hospital put worker in induced coma on a ventilator.
46	23 June 16	Central	NECC	Worker	A flag pole was being removed and the flag pole touch the wires above; live wire. The worker was holding the pole at the bottom and had an electrical shock
47	23 June 16	Western	PAVE	Worker	Worker was doing asphalt work in a parking lot near an asphalt cement tanker that has a heat transfer unit on it that keeps the asphalt warm. Worker went to climb on top of the truck to check up on it, a flame came up and burned the worker in the face. Worker was wearing a face shield, and that the face shield melted, resulting in burns to the face.
48	24 June 16	Western	RESS	Worker	Worker hit himself in the head with a hammer drill while fixing a lash machine. Worker suffered a loss of consciousness.
49	27 June 16	Eastern	INST	Worker	Worker was grabbing a set of windows from a stack when the stack fell on worker's leg. Broken leg
50	29 June 16	Eastern	COMM	Worker	Worker was going up a ladder but slipped and fell. Both arms broken.
51	5 July 16	Western	SEWW	Worker	A machine "flipped" over and hit a worker in the head causing the worker to lose consciousness
52	13 July 16	Central	INDU	Worker	Worker fractured pelvis from falling on beam.
53	14 July 16	Eastern	RAIL	Worker	Worker suffered an electrical shock- worker lost consciousness.
54	20 July 16	Eastern	ASB2	Worker	Worker fell off baker scaffold when a plank failed - worker sustained a fractured arm.
55	21 July 16	Northern	ROAD	Worker	Worker was welding a steel beam, the weld let go and the worker was hit by the beam when it fell. Broken leg.
56	26 July 16	Central	RESS	Worker	Worker fell 15' from a crank-up masonry scaffolding. Fractured arm.
57	30 July 16	Central West	RESS	Worker	Worker fractured ankle tripping over equipment
58	04 August 16	Eastern	COMM	Worker	The worker was cleaning a concrete pumping unit hopper when his hand got caught in the hopper blades severing his hand.
59	08 August 16	Eastern	RESM	Worker	Worker fell approx. 30 ft. when the scaffold system collapsed. Worker sustained fractures to both legs and back injuries.

F				T	
60	15 August 16	Central East	INDU	Worker	Worker moving dirt with a mini excavator, backed it up and caught his leg between the machine and curb. Worker sustained a broken leg.
61	15 August 16	Central West	PAVE	Worker	Worker struck by tongue of equipment trailer when tipped up; worker sustained fractured left arm.
62	18 August 16	Western	RESM	Worker	Worker sustained a fracture to the upper ulna bone in left arm after falling approximately 4 ft. off a ladder.
63	18 August 16	Central East	INST	Worker	Worker tripped and fell on a piece of rebar. Worker sustained a broken right forearm.
64	19 August 16	Central West	NECC	Worker	Worker was on a ladder and fell 12 feet. Worker fractured left knee
65	19 August 16	Northern	RESS	Worker	Two men fell off scaffolding working on house. One worker was unconscious upon falling
66	24 August 16	Central West	RESS	Worker	Worker was on while constructing a temporary work platform which collapsed. Worker fractured right leg
67	28 August 16	Western	COMM	Worker	Worker was pulling material during a demolition fell backwards, hit his head on the concrete floor and was unconscious
68	29 August 16	Western	RESS	Worker	Worker fell off ladder and suffered head trauma while roofing
69	01 Sept 16	Eastern	ROAD	Worker	Worker's leg was run over by a bulldozer that was backfilling
70	01 Sept 16	Central East	SEWW	Worker	Workers lost consciousness after being hit by fence blown over by wind
71	01 Sept 16	Western	RESM	Worker	Worker fell 24 ft from a scaffold and sustained severe head injuries
72	02 Sept 16	Eastern	RESS	Worker	Worker fell 20 ft. onto a lower second roof while roofing single family home
73	02 Sept 16	Central-West	RESS	Worker	Worker operating bobcat when it tipped over trapping him
74	07 Sept 16	Central- East	RESM	Worker	Worker was injured when he fell from a height of 8.6 ft. during installation of form-work decking.
75	09 Sept 16	Central-West	NECC	Worker	Worker was struck in the leg by the bucket of an excavator
76	14 Sept 16	Northern	RESS	Worker	Worker fell from ladder striking head resulting in loss of consciousness
77	14 Sept 16	Central-West	SEWW	Worker	Worker was using a cut off saw to cut wood, the saw "jumped up" at him and hit the worker in the right arm pit

	1	1	1 1		
78	15 Sept 16	Central-West	ROAD	Worker	Worker was struck by a vehicle when he was opening a lane of traffic on 403
79	15 Sept 16	Central-East	RESM	Worker	Worker who was on a ladder leaning against a 53 foot trailer fell with the ladder to the ground. Worker is said to have sustained unspecified injuries to the right hip and arm
80	20 Sept 16	Central-West	RESS	Worker	Worker fell from ladder 13 feet through wooden safety fence, fractured right hip and femur
81	21 Sept 16	Eastern	RESS	Worker	Worker fell off a ladder while installing siding, suffered a fractured leg.
82	26 Sept 16	West	ROAD	Worker	Worker burned by tar spill in back of truck
83	26 Sept 16	Central East	NECC	Worker	Worker climbing to the mezzanine/mechanical room fell from ladder falling onto cement floor
84	26 Sept 16	Central East	INDU	Worker	Worker was climbing a vertical access ladder, slipped and fell
85	27 Sept 16	West	NECC	Worker	Worker was refilling a three inch gas water pump when the front side of his body caught on fire
86	27 Sept 16	Central West	INST	Worker	Worker had a stack of doors fall on them when unloading from a truck.
87	29 Sept 16	Eastern	INST	Worker	Worker was moving a generator, generator shifted & pinned workers knee, fractured right leg
88	03 Oct 16	Eastern	RESS	Worker	Worker fell off a ladder approx. 8ft. hitting head on concrete floor suffering unconsciousness.
89	04 Oct 16	Central West	RESS	Worker	Worker fell 20 ft off a roof, sustained cracked skull and a broken vertebrae
90	04 Oct 16	West	WELL	Worker	Worker was struck on the head by a boom truck arm snapping off during the lifting a pellet of cement bags
91	05 Oct 16	Central West	RESS	Worker	Worker on a renovation project fell through the floor to the basement. Sustained fracture to skull and collarbone
92	05 Oct 16	West	ROAD	Worker	Worker suffered critical injuries when a road machine reversed and ran worker over
93	07 Oct 16	Central West	RESS	Worker	Worker fell off residential roof.
94	12 Oct 16	West	RESM	Worker	Worker was found unconscious laying at the bottom of the stairs, worker regained consciousness
95	17 Oct 16	Central East	INST	Worker	Worker slipped on concrete slab

18-Oct-16	Eastern	RESM	Worker	Worker installing plywood around a column, slipped & fell
21-Oct-16	Central West	NECC	Worker	Worker moving rebar from backhoe suffered broken leg
21 Oct 16	Eastern	RESS	Worker	Worker fell two storeys off the roof of a home, in and out of consciousness
22 Oct 16	West	COMM	Worker	Worker was on scaffolding applying masonry work to plaza and fell approx 20 feet through the scaffolding
24 Oct 16	Central West	RESM	Worker	Worker fell 16 feet when scaffolding collapsed. Worker sustained head and back injuries and suffered a loss of consciousness.
25 Oct 16	Central East	GRAD	Worker	Worker was doing waterproofing in an excavation. The east wall collapsed onto the worker. Worker sustained a fractured hip
26 Oct 16	Central East	RESS	Worker	Worker was working on a roof when he fell 6.3 m to the ground below and suffered a broken right leg and possible head injury
01-Nov-16	Eastern	POWP	Worker	Worker hit by falling rebar dowel on the head and loss consciousness
01-Nov-16	Eastern	RESM	Worker	Worker fell from roof onto parking garage breaking pelvis
02-Nov-16	Central-West	RESS	Worker	Worker was moving a truss on the roof, missed step, fell 10 ft to second floor, injury to right leg
04-Nov-16	Northern	ROAD	Worker	Worker fractured foot when panel being hoisted up, hit rebar and fell on workers foot
07-Nov-16	Northern	NECC	Worker	Worker loss consciousness
09-Nov-16	Central West	RESS	Worker	Worker fell from scaffold; lost consciousness, sustained head injuries
10-Nov-16	Central East	ROAD	Worker	Worker sustained an injury to his foot when a piece of track rail fell on it while being moved
11-Nov-16	Central East	COMM	Worker	Worker was building commercial building and cut arm on saw
14-Nov-16	Central West	INDU	Worker	Worker was struck by hoist crane that ran over right foot
15-Nov-16	Central West	COMM	Worker	Worker fell 25' through roof opening
16-Nov-16	West	EXCA	Worker	Worker was struck in the head by filler piece while stripping concrete form work, loss consciousness
	21-Oct-16 21 Oct 16 22 Oct 16 24 Oct 16 25 Oct 16 01-Nov-16 01-Nov-16 04-Nov-16 07-Nov-16 10-Nov-16 11-Nov-16 11-Nov-16	21-Oct-16 Central West 21 Oct 16 Eastern 22 Oct 16 West 24 Oct 16 Central West 25 Oct 16 Central East 01-Nov-16 Eastern 01-Nov-16 Eastern 02-Nov-16 Central-West 04-Nov-16 Northern 09-Nov-16 Central West 10-Nov-16 Central East 11-Nov-16 Central East 14-Nov-16 Central West 15-Nov-16 Central West	21-Oct-16 Central West NECC 21 Oct 16 Eastern RESS 22 Oct 16 West COMM 24 Oct 16 Central West RESM 25 Oct 16 Central East GRAD 26 Oct 16 Central East RESS 01-Nov-16 Eastern POWP 01-Nov-16 Central-West RESS 04-Nov-16 Northern ROAD 07-Nov-16 Central West RESS 10-Nov-16 Central East ROAD 11-Nov-16 Central East COMM 14-Nov-16 Central West INDU 15-Nov-16 Central West COMM	21-Oct-16 Central West NECC Worker 21 Oct 16 Eastern RESS Worker 22 Oct 16 West COMM Worker 24 Oct 16 Central West RESM Worker 25 Oct 16 Central East GRAD Worker 01-Nov-16 Eastern POWP Worker 01-Nov-16 Central-West RESS Worker 04-Nov-16 Northern ROAD Worker 07-Nov-16 Northern NECC Worker 10-Nov-16 Central East RESS Worker 11-Nov-16 Central East ROAD Worker 11-Nov-16 Central East ROAD Worker 11-Nov-16 Central East ROAD Worker

114	17-Nov-16	Central West	RESS	Worker	Worker fell while walking down a depression, tripped and fractured his leg
115	17-Nov-16	Central East	COMM	Worker	Worker fell 10 ft in a parking garage and fractured elbow
116	18-Nov-16	Central East	RESS	Worker	Worker tripped over cable and broke arm
117	24-Nov-16	Central East	COMM	Worker	Worker was installing electrical conduit, tripped and fell in 12" deep trench, fractured patella
118	25-Nov-16	Eastern	INST	Worker	Worker fell and broke ankle while entering the cab of his crane
119	25-Nov-16	Toronto West	COMM	Worker	Worker took heart attack at the construction site
120	26-Nov-16	Eastern	RESS	Worker	Worker fell from 11/2 storey roof
121	26-Nov-16	Central West	RESS	Worker	Worker was moving framed glass, upper section broke, fell on worker leg cutting thigh
122	28-Nov-16	Central-West	RESS	Worker	Worker lost footing fell into basement 25-27'
123	29-Nov-16	Western	SEWW	Worker	Worker fell off ramp and fractured arm
124	30-Nov-16	Central –East	INDU	Worker	Worker fell off formwork and hit head
125	30- Nov-16	Central East	COMM	Worker	Worker while acting as a spotter was struck by elevated work platform hitting heal and fracturing fibula
-	•				